

Information	<input type="checkbox"/>	Recommendation	<input type="checkbox"/>	Mandatory	<input checked="" type="checkbox"/>
--------------------	--------------------------	-----------------------	--------------------------	------------------	-------------------------------------

A/C AFFECTED	P2002 (series) all serial numbers
TIME OF COMPLIANCE	At the next service interval or within the next 10 hrs of flying
WORKING PLACE	On place.

Subject: *Landing gear bolts inspection.*

Scope: *A LSA mechanic, A&P mechanic, FAA Repair Station, or an authorized factory representative must inspect the landing gear attachment bolts.*

The visual inspection includes:

- *Attachment bolts: inspect the conditions and the torque value;*
- *Aluminium alloy clamp inspection for deformation or cracks;*

If the bolts must be replaced, please request to your TECNAM dealer the following P/N:

P/N	Description	Q.ty
MS20005-30	Lateral bolt	4
MS20006-30	Central bolt	2
MS21042-5	Self-locking nut	4
MS21042-6	Self-locking nut	2
MS20002-5	Plain washer	4
MS20002-6	Plain washer	2

Manpower: *1 man hour*

Required material: *Bolts replacement kit*

Tooling: *No special tools are required*

Weight and balance: *nil*

Instruction: *see instruction enclosed in the installation kit*

For further information, please contact Tecnam:

Tel +39 081 7583210; Fax +39 081 7584528; E-mail p.violetti@tecnam.com; m.oliva@tecnam.org